5/2/24, 5:52 PM Printer Friendly View



YMMS: 2006 Lexus GS 300 May 2, 2024

Engine: 3.0L Eng
License:
VIN:
Odometer:

MIL "ON" DTC P0751

TECHNICAL SERVICE BULLETIN

Reference Number(s): L-SB-0076-09 Rev1, Date of Issue: May 13, 2010

LEXUS: 2006 GS300 Service Category: Drivetrain

Section: Automatic Transmission/Transaxle

COPYRIGHT: © 2018 Lexus, a division of Toyota Motor Sales, USA License Agreement TMS1002

Superceded Bulletin(s): L-SB-0076-09 Rev1, Date of Issue: July 9, 2009

APPLICABILITY

APPLICABILITY

ADDITIONAL INFORMATION	MODEL(S)	YEAR(S)
Transmission(s): 6AT VDS(s): BH96S, CH96S	GS300	2006

NOTE: TSIB REVISION NOTICE

May 13, 2010 Rev 1:

 Parts Information has been updated with additional parts (oxygen sensor).

NOTE: Any previous printed versions of this service bulletin should be discarded.

INTRODUCTION

Some 2006 model year GS 300 vehicles may exhibit a MIL "ON" condition with DTC P0751 stored (Shift Solenoid "A" Performance). DTCs P2714 or P0894 may also be stored. The Engine Control Module/ECM (SAE term: Powertrain Control Module/PCM) detection logic for DTC P0751 has been revised to prevent false detection of P0751 and erroneous MIL "ON".

To properly address this condition, two different repair procedures are provided. Carefully review the Repair Procedure Overview below and all steps of this bulletin BEFORE beginning any repair.

REPAIR PROCEDURE OVERVIEW

- 1. Confirm stored DTCs and verify vehicle condition matches this bulletin.
- 2. Verify calibration ID to determine if this repair has already been performed.

- 3. Determine if Repair Procedure A or B should be performed.
 - 1. Repair Procedure A:
 - Replace ECM (PCM), rear oxygen sensors, and update ECM (PCM) calibration (as necessary).
 - 2. Repair Procedure B: Update ECM (PCM) calibration ONLY.

WARRANTY INFORMATION

WARRANTY INFORMATION

OP CODE	DESCRIPTION	TIME	DRIVETRAIN	OFP	T1	T2
EG7010	R & R LH & RH Oxygen Sensors, R & R ECM (PCM), and Recalibrate ECM (PCM) Engine [Repair Procedure A]	2.7	2WD	89661- 3035#	0.0	
EG/010			4WD	89661- 3036#		99
FC0020	D20 Recalibrate ECM (PCM) [Repair Procedure B]	0.5	2WD	89661- 3035#	8A	99
EG9020			4WD	89661- 3036#		

APPLICABLE WARRANTY

- This repair is covered under the Lexus Federal Emissions Warranty. This warranty is in effect for 96 months or 80,000 miles, whichever occurs first, from the vehicles in-service date.
- · Warranty application is limited to occurrence of the specified condition described in this bulletin.

PARTS INFORMATION

PARTS INFORMATION

MODEL	ENGINE	DRIVETRAIN	PREVIOUS PART NUMBER	CURRENT PART NUMBER	PART NAME	QTY
2006 GS 300 3GR-FSE	2WD	89666-30350 89666-30351 89666-30352 89666-30353	89666-30354	Computer, Engine	1 ⁽¹⁾	
	4WD	89666-30360 89666-30361 89666-30362 89666-30363	89666-30364	Control (ECM/PCM)	1 ⁽¹⁾	
	2WD	89465-30710	89465-30820	Sensor, Oxygen (RH, LH)	1	
		89465-30710	89465-30820	Sensor, Oxygen (RH)	1	
	4WD	89465-30720	89465-30830	Sensor, Oxygen (LH)	1	
-	-	-	N/A	00451-00001-LBL	Authorized Modifications Label	1

DO NOT replace the ECM (PCM) if only performing Repair Procedure B.

NOTE: Authorized Modification Labels may be ordered in packages of 25 from the Materials Distribution Center (MDC) through Dealer Daily - Dealer Support Materials Orders.

CALIBRATION IDENTIFICATION CHART

CALIBRATION IDENTIFICATION CHART

		ECM	PREVIOUS CA	NEW CALIBRATION ID	VDS		
MODEL DRIVETRAIN	(CPU) REFER TO REPAIR REFER TO	REFER TO REPAIR PROCEDURE B					
2006 GS 300	OMD (AIT)	Main	33065000 33065100	33065200 33065300	33065400	BH96S	
	2006 GS	2WD (A/T)	Sub	53044000 53044100	53044200	<u>53044300</u>	ы 1903
	4)A/D (A/T)	Main	33066000 33066100	33066200 33066300	33066400	CH96S	
		4WD (A/T)	Sub	53045000 53045100	53045200	<u>53045300</u>	CI 1903

REQUIRED TOOLS & EQUIPMENT

REQUIRED EQUIPMENT

REQUIRED EQUIPMENT	SUPPLIER	PART NUMBER	QTY
TIS Techstream* or Techstream Lite		TSPKG1	
NOTE: Software version 5.00.028 or later is required.	ADE	or TSLITEDLR01	1

NOTE:

- Additional TIS Techstream units may be ordered by calling Approved Dealer Equipment (ADE) at 1-800-368-6787.
- The Diagnostic Tester is NOT recommended for flash reprogramming with this calibration file. Please use TIS

5/2/24, 5:52 PM Printer Friendly View

Techstream or an approved J2534 interface to perform this update. Visit <u>techinfo.toyota.com</u> for more information regarding J2534 reprogramming.

Fig: Diagnostic Tester Warning



Courtesy of © TOYOTA, LICENSE AGREEMENT TMS 1002

REQUIRED TOOLS


SPECIAL SERVICE TOOLS (SST'S)	PART NUMBER	QTY
GR8 Battery Diagnostic Station ⁽¹⁾	00002-MCGR8	1
(1) Essential SST.		

NOTE: Additional SSTs may be ordered by calling 1-800-933-8335.

VERIFICATION PROCEDURE

- 1. Using TIS Techstream, check for DTC(s) stored in the ECM (PCM).
- 2. Confirm that DTC P0751 (Shift Solenoid "A" Performance Shift Solenoid S1) is stored as a current DTC.
- 3. Check the Freeze Frame Data for each DTC stored to confirm which DTC(s) set first. **HINT**
 - 1. The DTC that is stored first will have 5 frames of Freeze Frame Data stored (see Figure and Figure).

- 2. On vehicles with the original ECM (PCM) installed in the vehicle, 5 frames of Freeze Frame Data (titled -3, -2, -1, 0, and +1) will NOT be present and review of FFD values may not confirm which DTC set first.
 - Fig: Freeze Frame Data For P0751 With 5 Frames Of Data (Titled -3, -2, -1, 0, And 1)



Courtesy of © TOYOTA, LICENSE AGREEMENT TMS1002

_ 8 X Stored Data 2007 IS250 4GR-FSE Freeze Frame Data P2714 Pressure Control Solenoid "D" Performance or Stuck OFF Unit alculate Load Engine Speed Vehicle Speed 1894 Health Che ECT DTC/Monit Coolant Temp 24.7 Data 2 rpm Closed Throttle Position SM OFF Neutral Position SW Signal Stop Light Switch Battery Voltage TC and TE1 Idle Fuel Cut ٧ 14.1 FC TAU OFF Shift SW Status (R Range) Shift SW Status (P Range) Shift SW Status (N Range) Shift SW Status (D Range) OFF Sports Shift Up SW Sports Shift Down SW Sports Mode Selection S Pattern Switch (PWR/M) itch Status A/T Oil Temperature 1 Lock Up Lock Up Solenoid Status SLU Solenoid Status SLT Solenoid Status ON Engine Speed from EF 1894 Intake-Air Temp from EFI Coolant Temp from EFI Throttle Position from EFI Accel Position from EFI Engine Run Time me after DTC Cleared

Fig: Freeze Frame Data For P2714 With One Frame Of Data

Courtesy of © TOYOTA, LICENSE AGREEMENT TMS1002

Distance from DTC Clearer

Does P0751 have 5 frames of Freeze Frame Data?

1. YES - Go to step 4.

Expand>>

NO - This TSIB does NOT apply if a DTC other than P0751 has 5 frames of Freeze Frame
 Data. Refer to the Repair Manual and follow diagnostics for the first stored or primary DTC (the
 DTC with 5 frames of Freeze Frame Data).

mile

If NO DTC has 5 frames of Freeze Frame Data - Go to step 4.

All Data


 Clear all codes and test drive vehicle. Monitor vehicle during test drive and confirm if abnormal shifting or a MIL "ON" occurs.

Did abnormal shifting occur or did a MIL turn "ON" during the test drive?

- 1. **YES -** This TSIB does **NOT** apply. Use Techstream to confirm DTCs and follow Repair Manual diagnostic method for primary DTC, or refer to the Repair Manual for diagnostic method based on shifting abnormality observed during the test drive.
- 2. NO Go to step 5.
- 5. Refer to the Health Check information in Techstream and confirm if the CAL ID matches the "Previous Calibration ID" or "New Calibration ID" listed in the Calibration Information chart in this TSIB.
 Does the calibration ID in the ECM (PCM) match the New Calibration ID listed in this TSIB?
 - 1. **YES -** The recalibration in this bulletin has been previously performed. Refer to the Repair Manual for diagnosis.
 - NO Refer to the Calibration Information Chart to determine if Repair Procedure A or B applies.
 HINT

If an Authorized Modifications Label is affixed to the vehicle in the location shown in Figure, this can assist in determining which Repair Procedure is applicable.

Fig: Location Of Authorized Modifications Label



Courtesy of © TOYOTA, LICENSE AGREEMENT TMS1002

REPAIR PROCEDURE A

- 1. Confirm the calibration ID is applicable based on the Calibration Identification Chart in this bulletin.
- 2. Replace both rear oxygen sensors.

Refer to the Technical Information System (TIS), 2006 model year GS 300 Repair Manual:

- Engine/Hybrid System Emission Control "3GR-FSE Emission Control: Heated Oxygen Sensor (For Sensor 2): On-Vehicle Inspection"
- 2. Engine/Hybrid System Emission Control "3GR-FSE Emission Control: Heated Oxygen Sensor (For Sensor 2): Removal"
- 3. Engine/Hybrid System Emission Control "3GR-FSE Emission Control: Heated Oxygen Sensor (For Sensor 2): Installation"
- 3. Replace the ECM (PCM).

Refer to TIS, 2006 model year GS 300 Repair Manual:

- 1. Engine/Hybrid System Engine Control "3GR-FSE Engine Control System: ECM: Removal"
- 2. Engine/Hybrid System Engine Control "3GR-FSE Engine Control System: ECM: Installation"
- 4. Follow the procedures outlined in TSIB No. EG012-04, "Entering VIN During ECM (PCM) Replacement and/or DTC P0630," and write the VIN to the ECM (PCM).


NOTE: The new ECM (PCM) may be equipped with an OLD calibration ID.

- 5. Check the ECM calibration ID and flash reprogram the ECM (PCM) if necessary.
 - 1. Refer to Repair Procedure B for the ECM (PCM) reprogramming procedure.
- 6. The repair is complete. Test drive the vehicle to confirm normal operation.

REPAIR PROCEDURE B

- 1. Confirm the calibration ID is applicable based on the Calibration Identification Chart in this bulletin.
- 2. Check for the Authorized Modifications Label affixed to the vehicle in the location shown in Figure. Confirm if the ECM (PCM) calibration has been updated. If the calibration ID listed is NOT the latest ECM (PCM) calibration go to step 3.

Fig: Location Of Authorized Modifications Label On 2006 GS 300



Courtesy of © TOYOTA, LICENSE AGREEMENT TMS1002

3. Flash Reprogram the ECM (PCM).

NOTE:

- 1. The GR8 Battery Diagnostic Station MUST be used in Power Supply Mode to maintain battery voltage at 13.5 volts while flash reprogramming the vehicle.
- 2. For details on how to use the GR8 Battery Diagnostic Station, refer to the <u>GR8 Instruction Manual</u> located on the Technical Information System (TIS), Diagnostics - Battery.

Follow the procedures outlined in TSIB No. L-SB-0015-10, "Techstream ECU Flash Reprogramming Procedure", and flash the ECM (PCM) with the NEW calibration file update.

- 4. Install the Authorized Modifications Label.
 - A. Using a permanent marker, enter the following information on the label:
 - A. ECM part number [Refer to the Parts Information section for the CURRENT PART NUMBER]
 - B. Calibration ID(s) [Refer to the Calibration Identification Chartfor the NEW CALIBRATION ID]
 - C. Dealer Code
 - D. Repair Date
 - E. Change Authority [This TSIBnumber]
 - B. Affix the Authorized Modifications Label to the vehicle at the location shown in Figure. The Authorized Modifications Label is available through the MDC, P/N 00451-00001-LBL.
- 5. The repair is complete. Test drive the vehicle to confirm normal operation.

Reprinted Under License from Toyota Motor Sales, U.S.A., Inc., License Agreement TMS1002